
# **A COMPOSITES**


### **ALUCOBOND**<sup>®</sup> AXCENT





#### **DETAIL LEGEND**


- 1 PARAPET CONDITION
- 1A PARAPET OPTIONAL
- <sup>2</sup> HORIZONTAL JOINT
- BASE CONDITION
   OUTSIDE CORNER
- 5 WINDOW HEAD
- 5a WINDOW HEAD OPTIONAL
- 6 WINDOW SILL
- 6a WINDOW SILL OPTIONAL7 WINDOW JAMB
- 7a WINDOW JAMB OPTIONAL
- 8 VERTICAL JOINT
  9 INSIDE CORNER

## **A** COMPOSITES **ALUCOBOND**<sup>®</sup> AXCENT 1 PARAPET CAP **Ammmul** ALUCOBOND AXCENT 0.080"/0.063" FASTENER (BY INSTALLER) 0 SHIM (BY **INSTALLER**) **EXTERIOR** SHEATHING (BY OTHERS) WEATHER RESISTANT **BARRIER (BY** OTHERS) 2.00" https://www.alucobondusa.com/ info.usa@3acomposites.com 800-626-3365 Disclaimer Note: 3A COMPOSITES USA, INC. DOES NOT MAKE ANY WARRANTIES, EXPRESS OR IMPLIED INCLUDING MERCHANTABILITY AND FITNESS FOR PURPOSE. THIS INFORMATION IS GIVEN TO THE BEST OF OUR KNOWLEDGE BUT WITHOUT ANY OBLIGATION ON OUR PART.












## A COMPOSITES


























https://www.alucobondusa.com/

info.usa@3acomposites.com

800-626-3365

Disclaimer Note: 3A COMPOSITES USA, INC. DOES NOT MAKE ANY WARRANTIES, EXPRESS OR IMPLIED INCLUDING MERCHANTABILITY AND FITNESS FOR PURPOSE. THIS INFORMATION IS GIVEN TO THE BEST OF OUR KNOWLEDGE BUT WITHOUT ANY OBLIGATION ON OUR PART.